

EPA Testing Methods

	Arsenic	Barium	Boron	Lead	Selenium
EPA Method	200.7 /200.8	200.7 /200.8	200.7 /200.8	200.7 /200.8	200.7 /200.8
reporting limit	1.0 mg/kg	0.500 mg/kg	0.050 mg/kg	0.500 mg/kg	0.621 mg/kg